

Modification Highlights for VR-203-J and VR-204-J

Due to the nature of this Executive Order revision, this document is comprised of two sections to clearly categorize the changes incorporated.

Section 1: Veeder-Root Wireless, Pressure Management Control (PMC) and In-Station Diagnostic (ISD) Component Amendment

Executive Order

- Legal Language and Executive Order exhibits have been updated to reflect new revision level.
- Amended Exhibit 1 to include make, model and figures identifying Veeder-Root wireless components.
- Amended Exhibit 1 to include Veeder-Root PMC Software Version 1.04 for VR-203 and ISD Software Version 1.04 for VR-204.
- Amended Exhibit 2 of VR-204 to include wireless components.
- Amended Exhibit 3 to include revised Veeder-Root warranty language for wireless components including battery pack.

Installation, Operation, and Maintenance Manual

- Amended Sections 1, 12, 13, 14, and 15 of VR-203 and VR-204 to include revised Veeder-Root contractor training requirements.
- Amended Veeder-Root warranty language in Sections 12 and 15 of VR-203 and Section 12 in VR-204.
- Amended Section 4 of VR-203 and VR-204 to include Veeder-Root wireless component battery replacement alarm. Reformatted tables. Added footnotes 6 and 7 in ISD Alarm tables of VR-204. Note that the VST Green Machine, as referenced in footnote 6, is not certified at this time but was included as a placeholder.
- Amended Section 15 of VR-203 and Section 12 of VR-204 to include wireless component battery replace warning.
- Updated serial command report tables in Sections 12 and 15 of VR-203 and Section 12 of VR-204.
- Added a new Section 19, entitled “TLS RF Wireless 2 System (W2) Installation and Maintenance Guide” for both VR-203 and VR-204.

Section 2: Veeder-Root Increased Capacity Vapor Polisher Amendment

Executive Order

- Legal Language and Executive Order exhibits have been updated to reflect the new revision level.
- Amended Exhibit 1 to include Veeder-Root PMC Software Version 1.04 for VR-203 and ISD Software Version 1.04 for VR-204.

Installation, Operation, and Maintenance Manual

- Amended Section 4, alarm summary table to add a VP Emissions Warn and VP Emissions Fail for the Veeder-Root Increased Capacity Vapor Polisher.
- Amended Section 12 of VR-204 and Section 15 of VR-203 to add a VP Emissions Warn and VP Emissions Fail in the Alarm Summary tables for the Veeder-Root Increased Capacity Vapor Polisher. Also revised ISD and PMC set up, reports, diagnostics, and troubleshooting.
- Corrected the Alarm Posting and PMC Alarm Summary sections to reflect that PMC Sensor Fault has a red light indicator and both PMC Sensor Fault and PMC Setup alarms are stored in the priority alarm history in the TLS.