

Modification Highlights for Executive Order VR-203-L

Part I: Executive Order

Legal Language:

- Changed footers and headers to reference VR-203-L
- Page 2, changed equipment shall be inspected daily, weekly, quarterly, and annually to weekly, quarterly, and annually per IOM.
- Page 2, changed reference from VR-203-A to J to VR-203-A to K
- Page 4, changed reference in two places from VR-204-J to VR-204-K
- Page 4, change reference from February 11 to June 25
- Page 4, change reference from June 2011 to November 2011

All Exhibits

- Changed all footers and headers to reference VR-203-L

Exhibit 2:

- Page 6, item 6 changed language to indicate bulk plant operations are not allowed with this system
- Page 8, changed last sentence under Maintenance Records to Figure 2B-8,

Exhibit 10:

- Added instructions and figures if vapor pressure sensor is located on the vent stack
- Added procedures to retrieve pressure data from the Veeder-Root TLS when the system has no pressure management control (PMC) installed
- Added instructions and figures on how to disable and re-enable the various vapor processors when conducting this test

Part II: Changes to ARB Approved Installation, Operation, and Maintenance Manuals (IOM)

Section 4

- Added individual trouble shooting tables based on type of processor installed

Section 12:

- Added procedures to retrieve pressure data from the TLS when the system has no pressure management control (PMC) installed
- Added instructions on how to configure the TLS350 and the Hirt indicator panel so they can communicate as an external input alarm.

Sections 1-20

- Where applicable, updated headers and footers to reflect Revision L