

Executive Order G-70-70-AC

Figure 3-F

Healy Vapor Recovery System with Model 100 Jet Pumps
Wiring Instructions for Multi-Product Dispensers and Submerged Pump Control