CADAMP SCHEDULE 2003

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Field Blank
JANUARY ('03)	Q							Q							R	N						Q							Q			BH/Rich
FEBRUARY					Q							R	N						Q							Q						Rub/SJ
MARCH					Q							R	N						Q							Q						Wil/Oak
APRIL		Q							R	N						Q							Q							Q		Res/Cro
MAY							R	N						Q							Q							Q				BH/Liv
JUNE				R	N						Q							Q							Q							Rub/Ric
JULY		R	N						Q							Q							Q							R	N	Wil/SJ
AUGUST						Q							Q							Q							R	N				Res/Oak
SEPTEMBER			Q							Q							Q							R	N							BH/Cro
OCTOBER	Q							Q							Q							R	N						Q			Rub/Liv
NOVEMBER					Q							Q							R	N						Q						Wil/Ric
DECEMBER			Q							Q							R	N						Q							Q	Res/SJ

KEY:

N Begin new sampling moment

R QFF and PUF recovery and reload - samples to be shipped to lab within 24 hours

Q QFF change

Represents one full cycle from sampling start to retrieval of PUF.