



**Winston H. Hickox**  
Secretary for  
Environmental  
Protection

# Air Resources Board

**Alan C. Lloyd, Ph.D.**  
Chairman

2020 L Street • P.O. Box 2815 • Sacramento, California 95812 • www.arb.ca.gov



**Gray Davis**  
Governor

April 7, 1999

Paul Bauer  
Manager, Technical Services  
Healy Systems, Inc.  
17 Hampshire Drive  
Hudson, New Hampshire 03051


Dear Mr. Bauer:

99-04

## Approval of Healy Model HPV 1.5 Pressure Valve

You requested CARB approval of the Healy Model HPV1.5 Pressure Relief Valve. The valve has a pressure relief setting of 1.5" W.C. + 0.75" W.C. - 0.0" W.C. and is used exclusively with the Healy Model 6275 Vent Sensor assembly.

The Healy Model HPV1.5 pressure relief valve shall be installed in conformity with the manufacturer's instructions and all applicable codes. The manufacturer's name, model number, operating pressures, and maximum rated flow rate shall be incorporated as part of the adhesive backed UL Listing Mark. The Listing Mark shall be a UL approved adhesive label. All valves will be impact stamp date coded for lot identification.



As required by the certification Procedures for Gasoline Vapor Recovery Systems at Service Stations, the approvals of the three State agencies is a precondition to certification by the Air Resources Board. The appropriate letters of approval have been received and are listed as follows:

-Department of Food and Agriculture,  
Division of Measurement Standards  
August 30, 1995.

-Department of Occupational Safety and Health  
May 7, 1997

-Department of Forestry and Fire Protection  
Office of the State Fire Marshal  
Certification # GVRC 005:027:022, issued December 10, 1998

I find that the use of the Healy Model HPV1.5 pressure relief valve, when installed in accordance with the manufacturer's instructions and the conditions listed above, will not adversely affect the performance of the Healy Model 6275 Vent Sensor assembly. Therefore, the Healy Model HPV1.5 pressure relief valve is certified for use with Healy Model 6275 Vent Sensor assembly as specified in Executive Orders G-70-165 and G-70-186.

If you have any questions or wish to discuss this matter further, please call Paul Thalken at (916) 445-0383 or Laura McKinney at (916) 327-1525.

Sincerely,

**INTERNET VERSION**

James J. Morgester, Chief  
Compliance Division

cc:

Mr. Jim Johnston, Chairman,  
CAPCOA Vapor Recovery Committee  
Monterey Bay Unified APCD  
24580 Silver Cloud Ct.  
Monterey, CA 93940