

Modification Highlights for Executive Order VR-103-C

- Amended the EO and IOM to reflect the new P/V vent valve positive cracking pressure specification of 2.5 to 6.0 inches WC.
- Removed reference to the Extractor Assemblies and Extractor Coupling as well as the Ball Float Vent Valve in the EO and IOM.
- Added pictures to Exhibit 1 of the EO showing component identification location.
- Other minor editorial changes for clarification.