

**COMPANIES GRANTED EXEMPTION TO MARKET NEW AFTERMARKET CATALYTIC CONVERTERS IN CALIFORNIA BASED ON THE NEW REGULATIONS EFFECTIVE JANUARY 1, 2009 (See footnote for instructions)**

Company	EO/Date (Click on highlighted EO # to view document)	Series/Model	Vehicle Application Summary	
			Model Year	Make/Class
Walker Manufacturing Company. (dba Tenneco)  (734) 384-7824  * <a href="#">See Inspection Alert</a>	<a href="#">*D-182-37/12-31-08</a>	80600/80700	1995 & older	T-2 pre-OBD II Trucks
	<a href="#">*D-182-38/11-7-08</a>	81800/81600	1995 - 2004	Ford PC
	<a href="#">*D-182-39/11-27-08</a>	80400/80200	1995 & older	PC-2 pre-OBD II PC
	<a href="#">*D-182-41/12-24-08</a>	80300/80500	1995 & older	PC-1 pre-OBD II PC
	<a href="#">*D-182-42/12-24-08</a>	81500	1996 - 2003	Chrysler LDT2/MDV (TLEV)
	<a href="#">*D-182-43/12-24-08</a>	81500	1996 - 2000	GM PC & LDT1
	<a href="#">*D-182-44/12-31-08</a>	82100/82200	1997 - 2004	Ford LDT2/MDV
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1994 - 2004	VW/Audi PC
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1995 - 2004	GM PC/LDT1
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1995 - 2004	Honda PC/LDT1
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1995 - 2004	Mazda PC
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1995 - 2004	Mitsubishi PC/LDT1
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1995 - 1999	Nissan PC/LDT1
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1996 - 1998	Suzuki PC/LDT1
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1994 - 2004	Toyota PC/LDT1
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1996 - 2004	VW PC
	<a href="#">D-182-45/3-27-09</a>	81700/81900	1995 - 2004	Volvo PC
	<a href="#">D-182-46/4-27-09</a>	80100	1995 & older	T-1 pre-OBD II Trucks
	<a href="#">D-182-47/12-16-09</a>	81700	2000 - 2005	BMW LDT2/MDV
	<a href="#">D-182-47/12-16-09</a>	81700	2005	Chrysler MDV
	<a href="#">D-182-47/12-16-09</a>	81900	1995 - 2000	Ford LDT2/MDV
	<a href="#">D-182-47/12-16-09</a>	81700/81900	1995 - 2005	GM LDT2/MDV
	<a href="#">D-182-47/12-16-09</a>	81700	1999 - 2002	Honda LDT2
	<a href="#">D-182-47/12-16-09</a>	81700	1996 - 2003	Isuzu LDT2
	<a href="#">D-182-47/12-16-09</a>	81700/81900	1995 - 2004	Land Rover MDV
	<a href="#">D-182-47/12-16-09</a>	81900	1996	Mitsubishi LDT2
	<a href="#">D-182-47/12-16-09</a>	81900	1997 and 2003	Nissan LDT2
<a href="#">D-182-47/12-16-09</a>	81700/81900	1995 - 2002	Toyota LDT2/MDV	
<a href="#">D-182-47/12-16-09</a>	81700	1997 - 2003	VW LDT2	
<a href="#">D-182-47/12-16-09</a>	81700	2001 - 2002	Volvo LDT2	
Car Sound Exhaust System, Inc. (dba Magnaflow)  (949) 858-5900	<a href="#">D-193-65/1-15-09</a>	44000/41000	1996 - 2001	Ford PC
	<a href="#">D-193-65/1-15-09</a>	44000/41000	1995 - 2004	Mazda PC/LDT1
	<a href="#">D-193-65/1-15-09</a>	44000/41000	1995 - 2004	Nissan PC/LDT1
	<a href="#">D-193-65/1-15-09</a>	44000/41000	1995 - 2004	Toyota PC/LDT1
	<a href="#">D-193-66/1-15-09</a>	45000	1996 - 2004	Chrysler LDT2/MDV
	<a href="#">D-193-66/1-15-09</a>	45000	1997 - 2000	Ford LDT2
	<a href="#">D-193-66/1-15-09</a>	45000	1996 - 2003	GM LDT2/MDV
	<a href="#">D-193-67/1-15-09</a>	46000	1995 - 2003	Chrysler PC/LDT1
	<a href="#">D-193-67/1-15-09</a>	46000	1996 - 2003	GM PC/LDT1
	<a href="#">D-193-67/1-15-09</a>	46000	1995 - 2003	Honda PC/LDT1
	<a href="#">D-193-67/1-15-09</a>	46000	1995 - 2004	Mazda PC/LDT1
	<a href="#">D-193-67/1-15-09</a>	46000	1996 - 2000	MBZ PC
	<a href="#">D-193-67/1-15-09</a>	46000	1995 - 1999	Nissan PC/LDT1
	<a href="#">D-193-67/1-15-09</a>	46000	1995 - 2003	Toyota PC/LDT1
	<a href="#">D-193-67/1-15-09</a>	46000	1996 - 2001	Volvo PC
	<a href="#">D-193-67/1-15-09</a>	46000	1996 - 2003	VW/Audi PC
	<a href="#">D-193-68/1-15-09</a>	41100/41400	1994 - 2004	Ford PC/LDT1
	<a href="#">D-193-69/1-21-09</a>	46000	1996 - 2003	BMW PC
	<a href="#">D-193-84/11-27-08</a>	37000/38000	1995 & older	PC-2 pre-OBD II PC
	<a href="#">D-193-85/12-4-08</a>	39000	1995 & older	T-1 pre-OBD II Trucks
	<a href="#">D-193-86/11-27-08</a>	36000	1995 & older	PC-1 pre-OBD II PC
	<a href="#">D-193-87/12-17-08</a>	33000/34000	1995 & older	T-2 pre-OBD II Trucks
	<a href="#">D-193-88/09-15-09</a>	47100/47200	1996 - 2005	Ford LDT2 and MDV
	<a href="#">D-193-89/12-28-09</a>	46000	1996 - 2003	BMW PC
	<a href="#">D-193-89/12-28-09</a>	46000	1995 - 2003	Chrysler PC/LDT1
	<a href="#">D-193-89/12-28-09</a>	46000	1996 - 2005	GM PC/LDT1
	<a href="#">D-193-89/12-28-09</a>	46000	1995 - 2005	Honda PC/LDT1
<a href="#">D-193-89/12-28-09</a>	46000	1995 - 2005	Hyundai PC	
<a href="#">D-193-89/12-28-09</a>	46000	1998 - 1999	Isuzu LDT1	
<a href="#">D-193-89/12-28-09</a>	46000	1997 - 2004	Jaguar PC	
<a href="#">D-193-89/12-28-09</a>	46000	1995 - 2005	Kia PC/LDT1	

	<a href="#">D-193-89/12-28-09</a>	46000	1995 - 2005	Mazda PC/LDT1
	<a href="#">D-193-89/12-28-09</a>	46000	1996 - 2003	MBZ PC
	<a href="#">D-193-89/12-28-09</a>	46000	1995 - 2005	Mitsubish PC/LDT1
	<a href="#">D-193-89/12-28-09</a>	46000	1995 - 1999	Nissan PC/LDT1
	<a href="#">D-193-89/12-28-09</a>	46000	1996 - 1998	Suzuki PC/LDT1
	<a href="#">D-193-89/12-28-09</a>	46000	1996 - 2005	Toyota PC/LDT1
	<a href="#">D-193-89/12-28-09</a>	46000	1996 - 2004	Volvo PC
	<a href="#">D-193-89/12-28-09</a>	46000	1996 - 2005	VW PC
	<a href="#">D-193-89/12-28-09</a>	46000	1997 - 2005	Audi PC
<b>AirTek, Inc. (dba Catco)</b> (800) 247-2515	<a href="#">D-280-33/11-20-08</a>	110000	1999 - 2004	Hyundai PC
	<a href="#">D-280-42/4-14-09</a>	710000	1996 - 2004	Chrysler MDV
	<a href="#">D-280-42/4-14-09</a>	710000	1996 - 2004	Ford LDT2/MDV
	<a href="#">D-280-42/4-14-09</a>	710000	1996 - 2004	GM LDT2/MDV
	<a href="#">D-280-42/4-14-09</a>	710000	1996 - 2003	Isuzu/Honda LDT2
	<a href="#">D-280-42/4-14-09</a>	710000	1996 - 2004	Mitsubishi LDT2
	<a href="#">D-280-42/4-14-09</a>	710000	1998 - 2004	Nissan LDT2
	<a href="#">D-280-42/4-14-09</a>	710000	1995 - 2004	Toyota LDT2
	<a href="#">D-280-43/11-18-08</a>	610000/510000	1994 - 2004	Ford PC
	<a href="#">D-280-46/12-8-08</a>	710000	1996 - 2000	Chrysler LDT2/MDV
	<a href="#">D-280-47/12-24-08</a>	91000	1995 & older	T-1 pre-OBD II Trucks
	<a href="#">D-280-48/12-23-08</a>	66000	1995 & older	PC-2 pre-OBD II PC
	<a href="#">D-280-52/12-8-08</a>	610000	1996 - 2002	Ford PC
	<a href="#">D-280-53/11-24-08</a>	110000/710000	1998 - 2002	GM LDT1
	<a href="#">D-280-62/12-9-08</a>	610000	1996 - 2000	1.6L Honda Civics
	<a href="#">D-280-72/12-17-08</a>	65000	1995 & older	PC-1 pre-OBD II PC
	<a href="#">D-280-73/3-27-09</a>	610000	1995 - 2003	Ford PC/LDT1
	<a href="#">D-280-73/3-27-09</a>	610000	1996 - 2004	Subaru PC
	<a href="#">D-280-73/3-27-09</a>	610000	1996 - 2001	Toyota PC/LDT1
	<a href="#">D-280-73/3-27-09</a>	610000	1996 - 2004	Ford/Mazda PC/LDT1
	<a href="#">D-280-73/3-27-09</a>	610000	1995 - 2001	Nissan PC/LDT1
	<a href="#">D-280-73/3-27-09</a>	610000	1995 - 2002	Suzuki PC/LDT1
	<a href="#">D-280-73/3-27-09</a>	610000	1996 - 2004	Hyundai PC
	<a href="#">D-280-73/3-27-09</a>	610000	1995 - 2003	GM PC
	<a href="#">D-280-73/3-27-09</a>	610000	1996 - 2004	Mitsubishi PC/LDT1
	<a href="#">D-280-77/4-16-09</a>	110000/610000	1999 - 2002	Toyota PC
	<a href="#">D-280-77/4-16-09</a>	110000/610000	1996 - 2004	Jaguar PC
	<a href="#">D-280-77/4-16-09</a>	110000/610000	1995 - 2004	Kia PC/LDT1
	<a href="#">D-280-77/4-16-09</a>	110000/610000	1996 - 2002	Chrysler LDT1
	<a href="#">D-280-78/4-16-09</a>	410000	1996 - 2002	Honda/Acura PC/LDT1
	<a href="#">D-280-78/4-16-09</a>	410000	1996 - 2004	VW/Audi PC
	<a href="#">D-280-78/4-16-09</a>	410000	1996 - 2003	Volvo PC
	<a href="#">D-280-78/4-16-09</a>	410000	1996 - 2003	Chrysler PC
	<a href="#">D-280-78/4-16-09</a>	410000	1996 - 2000	BMW PC
	<a href="#">D-280-78/4-16-09</a>	410000	1995 - 2000	Toyota-Lexus PC
	<a href="#">D-280-78/4-16-09</a>	410000	1995 - 2002	MBZ PC
	<a href="#">D-280-79/4-16-09</a>	110000/410000	1996 - 2004	GM PC
	<a href="#">D-280-79/4-16-09</a>	110000/410000	1996 - 2003	Mazda PC
	<a href="#">D-280-80/2-28-09</a>	91000	1995 & older	T-2 pre-OBD II Trucks
<b>Miller Catalyzer Corporation</b> (510) 732-0622	<a href="#">D-353-39/2-5-09</a>	60000	1995 - 2003	Chrysler PC/LDT1
	<a href="#">D-353-39/2-5-09</a>	60000	1995 - 2004	GM PC LDT1
	<a href="#">D-353-39/2-5-09</a>	60000	1995 - 1999	Mitsubishi/Eagle/Chrysler
	<a href="#">D-353-39/2-5-09</a>	60000	1996 - 2001	Nissan PC/LDT1
	<a href="#">D-353-39/2-5-09</a>	60000	1995 - 2004	Volvo PC
	<a href="#">D-353-39/2-5-09</a>	60000	1995 - 2002	Toyota PC/LDT1
	<a href="#">D-353-39/2-5-09</a>	60000	1995 - 2004	Ford PC/LDT1
	<a href="#">D-353-39/2-5-09</a>	60000	1995 - 2004	BMW PC
	<a href="#">D-353-40/2-5-09</a>	31000	1995 - 2003	GM LDT2/MDV
	<a href="#">D-353-40/2-5-09</a>	31000	1996 - 2003	GM MDV
	<a href="#">D-353-40/2-5-09</a>	31000	1995 - 1999	Toyota LDT2
	<a href="#">D-353-40/2-5-09</a>	31000	1996 - 2003	Chrysler LDT2/MDV
	<a href="#">D-353-40/2-5-09</a>	31000	1999 - 2003	Honda LDT2
	<a href="#">D-353-40/2-5-09</a>	31000	1995 - 2004	Land Rover LDT2/MDV
	<a href="#">D-353-42/2-5-09</a>	45000/61000	1995 - 2004	Ford LDT2/MDV
	<a href="#">D-353-42/2-5-09</a>	45000/61000	1995 - 2004	Toyota LDT2/MDV
	<a href="#">D-353-42/2-5-09</a>	45000/61000	1997 - 2003	Chrysler LDT2/MDV
	<a href="#">D-353-42/2-5-09</a>	45000/61000	1996 - 2004	Nissan LDT2
	<a href="#">D-353-61/12-22/08</a>	12000/11000	1995 - 2004	MBZ PC
	<a href="#">D-353-47/6-11-09</a>	59000	1995 & older	T-1 pre-OBD II Trucks
	<a href="#">D-353-62/6-22-09</a>	69000	1995 & older	PC-1 pre-OBD II PC

<b>International Muffler Company (d.b.a. Maremont)</b>  (865) 458-4681	<a href="#">D-560-1/4-27-09</a>	655000/655500	1996 - 2002	Ford LDT2/MDV
	<a href="#">D-560-2/1-7-10</a>	656800/656900	1995 - 2005	Ford LDT2/MDV
	<a href="#">D-560-2/1-7-10</a>	656800/656900	1995 - 2003	Mazda LDT2
	<a href="#">D-560-2/1-7-10</a>	656800/656900	1996 - 2002	Nissan LDT2
<b>Valina, Inc. (dba CarTex)</b>  (323) 269-2577	<a href="#">D-562-12/1-20-09</a>	23000	1995 & older	T-1 pre-OBD II Trucks
	<a href="#">D-562-13/12-31-08</a>	12600	1996 - 2003	Chrysler MDV
	<a href="#">D-562-14/12-19-08</a>	12200	1996 - 2003	GM MDV
	<a href="#">D-562-15/12-31-08</a>	12300/12100	1997 - 2004	Ford MDV
	<a href="#">D-562-16/12-31-08</a>	12600	1996 - 2003	GM MDV
	<a href="#">D-562-17/1-15-09</a>	12700/12100	1997 - 2003	Ford LDT2
	<a href="#">D-562-18/12-31-08</a>	12400	1996 - 2004	Honda/Acura PC
	<a href="#">D-562-20/12-4-08</a>	12800	1996 - 2000	1.6L Honda Civics
	<a href="#">D-562-23/2-24-09</a>	12400	1996 - 2004	VW/Audi PC
	<a href="#">D-562-24/2-24-09</a>	12500	1996 - 2003	BMW PC
	<a href="#">D-562-25/2-24-09</a>	12500	1996 - 2004	Volvo PC
	<a href="#">D-562-27/3-19-09</a>	12700/12100	1996 - 2003	Isuzu/Honda LDT2
	<a href="#">D-562-28/2-24-09</a>	12700/12100	1998 - 2004	Nissan LDT2
	<a href="#">D-562-29/2-27-09</a>	12700/12100	1995 - 2004	Toyota LDT2
	<a href="#">D-562-30/3-13-09</a>	12300/12100	1995 - 2004	Toyota MDV
	<a href="#">D-562-31/2-24-09</a>	12200	1996 - 2004	GM MDV
	<a href="#">D-562-32/4-27-09</a>	12500	1995 - 2003	Chrysler PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	1994 - 2004	Ford PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	1996 - 2003	GM PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	1996 - 2004	Jaguar PC
	<a href="#">D-562-32/4-27-09</a>	12500	1995 - 2004	Kia PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	1995 - 2004	Mazda PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	1996 - 2000	MBZ PC
	<a href="#">D-562-32/4-27-09</a>	12500	1996 - 2004	Mitsubishi PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	1995 - 1999	Nissan PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	2001 - 2004	Subaru PC
	<a href="#">D-562-32/4-27-09</a>	12500	1995 - 2002	Suzuki PC/LDT1
	<a href="#">D-562-32/4-27-09</a>	12500	1995 - 2004	Toyota PC/LDT1
	<a href="#">D-562-33/4-23-09</a>	12300/12100	1997 - 2004	Ford MDV
	<a href="#">D-562-34/4-23-09</a>	12600	1996 - 2004	Ford MDV
	<a href="#">D-562-35/7-7-09</a>	12600	1996 - 2004	Chrysler MDV
	<a href="#">D-562-36/7-7-09</a>	12200	1996 - 2004	GM MDV
	<a href="#">D-562-37/10-19-09</a>	13300	1995 - 2005	GM PC/LDT1
<a href="#">D-562-37/10-19-09</a>	13300	1996 - 2001	Isuzu LDT1	
<a href="#">D-562-37/10-19-09</a>	13300	1996 - 2003	Saab PC	
<a href="#">D-562-38/12-10-09</a>	13100/13200	1994 - 2004	Ford PC/LDT1	
<a href="#">D-562-38/12-10-09</a>	13100/13200	1995 - 2004	Mazda LDT1	
<a href="#">D-562-39/12-16-09</a>	21000	1995 & older	PC-1 pre-OBD II PC	
<a href="#">D-562-40/12-29-09</a>	22000/2600	1995 & older	PC-2 pre-OBD II PC	
<a href="#">D-562-41/1-26-10</a>	13400/13500	1996 - 2005	Ford MDV	
<a href="#">D-562-42/1-29-10</a>	24000/25000	1995 & older	T-2 pre-OBD II Trucks	
<b>Active Exhaust Corporation</b> (416) 445-9610	<a href="#">D-646-1/5-29-09</a>	44000	1995 - 2003	Toyota PC/LDT1
<b>Equipo Industrial Automotriz S.A. de C.V.</b> 011-525557168760	<a href="#">D-523-3/11-19-09</a>	80000	1996 - 2000	Honda/Acura PC
<b>Eastern Manufacturing, Inc.</b> (215) 702-3600	<a href="#">D-665/9-24-09</a>	840100	1996 - 1998	Honda/Acura PC
	<a href="#">D-665-1/2-2-10</a>	850200	1996 - 2002	GM PC/LDT1
	<a href="#">D-665-2/2-4-10</a>	863000	1995 & older	T-1 pre-OBD II Trucks

**Footnotes:****How to use this table**

1. Find vehicle make and model year from the two last columns
2. Find the corresponding EO from the second column
3. Click on the EO, if shown as a link, or enter the information in ARB web site to see the list of vehicles covered by the EO.  
**ARB WEB SITE:** [www.arb.ca.gov/msprog/aftermkt/devices/amquery.php](http://www.arb.ca.gov/msprog/aftermkt/devices/amquery.php)
4. Click on **VIEW PDF** and scroll down to the list of vehicles.

5. Compare the engine test group (engine family) from the underhood label on your vehicle to the ones listed in the EO to ensure that there is a match.

**New Label Requirements**

The label on the catalytic converter shell must be ½ inch high and large enough to be read from a distance of 5 feet from either side of the vehicle. The label must show the EO, specific part number (universal or direct-fit) for the vehicle, and date of production (month and year). In assigning specific part numbers, manufacturers have taken into consideration each vehicles exhaust configuration, including the location of the oxygen sensors, pipe size, etc. Therefore, no modifications should be required to fit a catalytic converter on a vehicle other than weld it in, where necessary.

**What is Legal for Sale by January 1, 2009?**

Only aftermarket catalytic converters that meet the new regulations can be sold and installed on appropriate vehicles in California. Previously exempted OBD II catalytic converters not sold and installed by the above date must be returned to manufacturers for compliant label and warranty card.

**List Updated: 2/8/10** (The list will be updated on a regular basis as new or update exemption applications are received).

For further information, please call: 1-800-242-4450