

**AIR RESOURCES BOARD**2020 L STREET  
P.O. BOX 2815  
SACRAMENTO, CA 95812

June 13, 1994

Mr. Ron Cleveringa  
Project Development Manager  
Enterprise Brass Works, Inc.  
Post Office Box 689  
Muskegon, Michigan 49443

#94-12

Dear Mr. Cleveringa:

Approval of the EBW 303-301 Coaxial Splitter Manifold

You requested California Air Resources Board (CARB) approval of the Enterprise Brass Works (EBW) Incorporated Model 303-301 coaxial splitter manifold.

The 303-301 splitter manifold is designed to retrofit existing conventional dispensers to coaxial capabilities. The fitting is an assembly intended for use in positive displacement or vacuum assisted motor fuel vapor recovery installations. It provides a means of coupling certified vapor recovery product hose assemblies to the vapor and fuel lines of a dispensing device.

The 303-301 splitter manifold is intended for installation on gasoline dispensing devices with coaxial hose vapor recovery systems. The unit shall be installed in conformity to the manufacturer's instructions and all applicable codes. The listee's name, model number, fuel port and vapor port shall be cast in the body of the fitting. The Underwriters Laboratories (UL) Incorporated label shall be affixed to the connector fittings body.

As required by the Air Resources Board certification procedures, you requested the approval of the Division of Occupational Safety and Health, the Office of the State Fire Marshal and the Department of Food and Agriculture, Division of Measurement Standards. The necessary approvals have been obtained from these agencies.

I find that the use of the 303-301 splitter manifold, when installed in accordance with the manufacturer's instructions and the conditions listed above, will not adversely affect the performance of vapor recovery systems on which it is installed. Therefore, the EBW Model 303-301 coaxial splitter manifold fitting is certified for use with Phase II vapor recovery systems.

Mr. Ron Cleveringa

-2-

June 13, 1994

Should you have any questions or need further assistance, please contact Mr. Basharat Iqbal at (916) 324-7343 or Ms. Laura Sullivan McKinney at (916) 327-1525.

Sincerely,



James J. Morgester, Chief  
Compliance Division

cc: Mr. Kenneth Kunaniec, Chairman  
CAPCOA Vapor Recovery Committee

Mr. Gary Hunter, Manager  
CARB Compliance Assistance Section