


Executive Order G-70-169-AA

Exhibit 2

Figure 2D

Proper Installation of the A/L Adaptor

Correct Installation: Note that the o-ring has isolated the shut-off port from the vapor holes



Incorrect Installation: Note that the o-ring includes the shut-off port with the vapor holes

