


Executive Order G-70-179
Exhibit 2
Figure 2B

Proper Installation of the A/L Adaptor

Correct Installation: Note that the o-ring has isolated the shut-off port from the vapor holes



Incorrect Installation: Note that the o-ring includes the shut-off port with the vapor holes

